

QUALITY CONTROL

BR No:


10/13-14 dt: 30/4/2013

Name of the Work:

Construction of R.C.C. Drain and Covering
Slab in Kalahasthinagar Railway Mani
House to Pampa Mahakavi road in W.M.M.
T-Dasarahalli Sub-division.

On verification of quality control test reports available in the file and also from inspection report of Technical Team Deployed for this purpose generally the work executed is satisfactory. Compliance of Quality Control Test Reports as per MORT&H at this stage is not feasible since this work was executed 2 years back.


Assistant Executive Engineer
Dasarahalli Sub Division
Bruhat Bengaluru Mahanagara Palike


Executive Engineer
Dasarahalli Division, Dasarahalli Zone
Bruhat Bengaluru Mahanagara Palike

ROAD HISTORY

BR No:

10/13-14 dt. 30/4/2013

Name of the Work:

Construction of R.C.C. Drain and Covering
Slab in Kalarthinagar Railway station House
to pumpa Mahakavi road in ward-15
T. Dasarahalli Sub-division.

Due to frequent delimitation of ward's the roads in this ward are bifurcated and distributed among different wards, Hence History of these/this road could not be maintained. Now road History is being uploaded to GIS and will be maintained regularly.



Assistant Executive Engineer
Dasarahalli Sub Division
Bruhat Bengaluru Mahanagara Palike



Executive Engineer
Dasarahalli Division, Dasarahalli Zone
Bruhat Bengaluru Mahanagara Palike